

PEC+ firmware version 1.02

December 28, 2007

Affected products

PEC+ and K310003 (PEC+ display kit) with firmware version 1.01 and earlier.

PEC+ controls made before 2006-10-23 are not affected.



Issues

New feature: advanced duty cycles

Advanced duty cycles function similar to normal duty cycles, but have an additional second set point that is higher than the set point 1.

When the temperature is above set point 2, the duty cycle remains on regardless of the on/off durations. When the temperature drops below set point 2, the duty cycle starts again.

Control flashes when setting curtain durations

Some controls flash when setting curtain 'on' and 'off' durations, preventing the settings from being programmed. Other areas of the control are not affected.

This update is required only for controls that display this symptom. It is NOT necessary to update controls that do not have this symptom.

Resolution

Upgrade any affected PEC+ controls or display kits to version 1.02 using a PEC+ Updater.

- ◆ For more information about the PEC+ Updater (PEC+U), see your dealer or visit www.phason.ca.
- ◆ To purchase or upgrade an existing PEC+ Updater, contact your dealer or Phason.

2 Terracon Place

Winnipeg, Manitoba, Canada
R2J 4G7

Phone: 204-233-1400
Fax: 204-233-3252

E-mail: support@phason.ca
Web site: www.phason.ca