

## Supra version 3.00 release

November 19, 2009

### Summary

The Supra firmware version has changed to v3.00 to make it compatible with component changes on the control board. It is functionally the same as v2.00 and no new features have been added.

As of Aug 12, 2009 all new Supras are v3.00. We will continue to support v2.00 and provide updates to fix any bugs that are found.



### Using the Intaglio

All Supra boards with serial number 20090812 *and higher* support firmware v3.x. They cannot be loaded with v2.x or older and the message below will appear if this is attempted.

**“This Supra is not compatible with this version. Press BACK”**

All Supra boards with serial number *lower than* 20090812 support v2.x. They cannot be upgraded to v3.x and the message below will appear if this is attempted.

**“This Intaglio does not contain valid data. Key=21947. Press BACK”**

If you have any questions, please contact Phason Customer Support.

Phason Inc.  
2 Terracon Place  
Winnipeg, Manitoba, Canada  
R2J 4G7

Phone: 204-233-1400  
Fax: 204-233-3252

E-mail: support@phason.ca  
Web site: www.phason.ca